



 This Replacement
Part# ST26374-2
Can be used in place
Of the original discontinued

1" LOCK COLLAR - DRIVE SHAFT

ST26374-2

2143319

ITEM	PART #	QTY	DESCRIPTION	ITEM	PART #	QTY	DESCRIPTION	
21393	1	26351	1	Frame	20	26406	1	Ring Gear
2	26096	1	Tow Pole	21	46012	1	Vise-Grip Plug 21373	
3	32073	2	Bearing	22	34621	1	Sheave - 12"	
4	26389	1	Drive Shaft only	23	34623	1	Belt - 4 hp. B & S, 4 hp. Kohler	
5	26521	1	Pinion/Drive Shaft Assembly	23	34622	1	Belt - 3/4 hp. Electric	
6		2	Castellated Nut - 3/4-16	24	34620	1	Sheave - 6", B & S, Kohler	
7		1	Castellated Nut - 1-14	24	34172	1	Sheave - 3/4 hp. Electric	
8	26374	1	Tilt-Trunnion Assembly	25	26381	1	Motor Base	
9	44020	1	Spring	26	30025	1	Engine, B & S	
10	26380	1	Handle - Tilt	26	30048	1	Engine, Kohler	
11	47023	1	Grip	27	31202	1	Motor, 3/4 hp. Electric	
12	46012	2	Lube Fitting	28	48016	1	Cord (electric)	
13	47001	2	Lube Cap	29	48019	1	Plug (electric)	
14	26365	1	Yoke	30	26392	1	Cowl - top	
15	32052	3	Seal	31	26384	1	Cowl - rear	
16	40019	6	Bearing Cone 32076	32	34573	2	Dust Cap	
17	*40020	6	Bearing Cup 32075	33	34018	2	4.00 x 12 Tire and Rim	
18	26371	1	Trunnion	34	34501	2	Hub	
	26400	1	Drum	35	26429	1	Spindle Assembly	

*For convenience - order Bearing # 32051